

FIG. 1






Takahisa TANAKA
Threading Control Method and Apparatus Therefor Q86219
April 15, 2005
(202) 2937060
Sheet 3 of 8

3/8

## FIG. 3




F⊿Ts :MAIN-SPINDLE MOVEMENT AMOUNT PER CONTROL CYCLE
F⊿Tsc:POST-CORRECTION MAIN-SPINDLE MOVEMENT AMOUNT PER
CONTROL CYCLE


F⊿Tz:THREADING-SPINDLE MOVEMENT AMOUNT PER CONTROL CYCLE F⊿To:THREADING-SPINDLE MOVEMENT AMOUNT AT FIRST INTERPOLATION


F\_Tn:THREADING-SPINDLE MOVEMENT AMOUNT AT SECOND AND SUBSEQUENT INTERPOLATIONS

F⊿TI:THREADING-SPINDLE MOVEMENT AMOUNT AT FINAL INTERPOLATION ⊿T:CONTROL CYCLE

FIG. 4







F $\overline{\Delta}$ To : THREADING-SPINDLE MOVEMENT AMOUNT AT FIRST INTERPOLATION F $\Delta$ Tn : THREADING-SPINDLE MOVEMENT AMOUNT AT SECOND AND SUBSEQUENT INTERPOLATIONS AT: CONTROL CYCLE ZPn ⊹ P )

ĀPo : FIRST MĀIN-SPĪNDLE POSITION CHANGE AMOUNT (NUMBER OF PULSES) △Pn : SECOND AND SUBSEQUENT MAIN-SPINDLE POSITION CHANGE AMOUNTS (NUMBER OF PULSES) P : NUMBER OF PULSES PER SINGLE MAIN-SPINDLE ROTATION

THREAD LEAD

FIG. 7

